ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್,
ನಂ. 1 ಕಟ್ಟಡಗಳ ಉಪ ವಿಭಾಗ, ವಿ.ವಿ ಕೇಂದ್ರ,
ಬೆಂಗಳೂರು ರವರ ಕಾರ್ಯಾಲಯ

ದೂರವಾಣಿ 22863305
e-mail :aee1vvtower@gmail.com

ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ

ಸಂ: ಸಕಾಇಂ/ನಂ.1ಕ.ಉ.ವಿ/ಕಿ.ಇಂ-1/2026-27/ ದಿನಾಂಕ:

ಇವರಿಗೆ,

The Principal,
Christ School (CBSE Syllabus),
Dharmaram College P.O.,
Suddagunte Palya,
Bangalore - 560029.

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರವರ ಕಛೇರಿ ಡಿವಿ॥ ಅಂಬೇಡಕರ್ ವೀದಿ ನಂ 525 ಕಾ॥ 20/08/26 ಬೆಂಗಳೂರು. ನಂ.1, ಕಟ್ಟಡಗಳ ಉಪವಿಭಾಗ ವಿ.ವಿ.ಕೇಂದ್ರ

ಮಾನ್ಯರೇ,

ವಿಷಯ : Christ School (CBSE Syllabus), ಕಟ್ಟಡಕ್ಕೆ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ನೀಡುವ ಬಗ್ಗೆ.

ಉಲ್ಲೇಖ :1) Christ School (CBSE Syllabus), ರವರ ಪತ್ರ ದಿನಾಂಕ: 17-08-2026
2) ಸರ್ಕಾರದ ಆದೇಶ ಸಂಖ್ಯೆ: ಲೋ.ಇ/59/ಜಿ.ಇ.ಡಿ/2019/ದಿನಾಂಕ: 07-05-2022.

* * * * * *

ಮೇಲ್ಕಂಡ ವಿಷಯಕ್ಕೆ ಸಂಬಂಧಿಸಿದಂತೆ, Christ School (CBSE Syllabus), Dharmaram College P.O., Suddagunte Palya, Bangalore - 560029 ಕಟ್ಟಡದ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ಶೈಕ್ಷಣಿಕ ಉದ್ದೇಶಕ್ಕಾಗಿ ಒದಗಿಸಲು ಅಗತ್ಯವಿರುವುದಾಗಿ ತಿಳಿಸಿ ಕಟ್ಟಡದ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರ ನೀಡಲು ಉಲ್ಲೇಖ (1)ರ ತಮ್ಮ ಪತ್ರದಲ್ಲಿ ಕೋರಲಾಗಿರುತ್ತದೆ. ಹಾಗೂ ಸದರಿ ಕಟ್ಟಡಕ್ಕೆ ಸಂಬಂಧಿಸಿದ ದಾಖಲೆಗಳನ್ನು ಈ ಕಛೇರಿಗೆ ಸಲ್ಲಿಸಲಾಗಿರುತ್ತದೆ.

ಅದರಂತೆ, ಶಾಲಾ ಕಟ್ಟಡವನ್ನು ದಿನಾಂಕ: 20-08-2026 ರಂದು ಉಪವಿಭಾಗದ ಪತಿಯಿಂದ ಪರಿವೀಕ್ಷಣೆ ನಡೆಸಲಾಗಿರುತ್ತದೆ. ಹಾಗೂ ಉಲ್ಲೇಖ (2)ರ ಸರ್ಕಾರದ ಆದೇಶದನ್ವಯ ನಗರ ಪ್ರದೇಶದಲ್ಲಿನ ಶಾಲೆಯ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ನೀಡಲು ರೂ. 5,000/- ಗಳ ಮೊತ್ತವನ್ನು The Assistant Executive Engineer, No. 1 Buildings Sub-division, V.V. Centre, Bangalore ರವರ ಹೆಸರಿನಲ್ಲಿ ಏಜಾನೆ-2 ಮುಖಾಂತರ ಪಾವತಿಸಿ ಚಲನ್ ಸಂಖ್ಯೆ: GR0826021600248777 ನ್ನು ಈ ಕಛೇರಿಗೆ ಸಲ್ಲಿಸಿರುತ್ತೀರಿ.

ಸದರಿ ಕಟ್ಟಡದ ಸಂಕೀರ್ಣವು ನೆಲಮಹಡಿಯಲ್ಲಿ 01 ಹಾಲ್, 01 ಪ್ರಾಂಶುಪಾಲರ ಕೊಠಡಿ, 01 ಪ್ರೇಯರ್ ಹಾಲ್, 01 ಕೌನ್ಸೆಲಿಂಗ್ ರೂಂ, 03 ಸ್ಟೋರ್ ರೂಂ, 01 ಸಿಬ್ಬಂದಿಗಳ ಕೊಠಡಿ, 01 ಉಪ ಪ್ರಾಂಶುಪಾಲರ ಕೊಠಡಿ, 05 ತರಗತಿ ಕೊಠಡಿ, 01 ಆಡಿಟೋರಿಯಂ, 01 ಕಾನ್ಫರೆನ್ಸ್ ಹಾಲ್, 01 ಟ್ರಸ್ಟಿನ ಕಛೇರಿ, ಬಾಲಕರಿಗಾಗಿ ಮತ್ತು ಬಾಲಕಿಯರಿಗಾಗಿ ಶೌಚಾಲಯವಿರುತ್ತದೆ. ಮೊದಲನೇ ಮಹಡಿಯಲ್ಲಿ 16 ತರಗತಿ ಕೊಠಡಿ, 01 ಸಿಬ್ಬಂದಿಗಳ ಕೊಠಡಿ, 02 ಸ್ಟೋರ್ ರೂಂ, ಬಾಲಕರಿಗಾಗಿ ಮತ್ತು ಬಾಲಕಿಯರಿಗಾಗಿ ಶೌಚಾಲಯವಿರುತ್ತದೆ. ಎರಡನೇ ಮಹಡಿಯಲ್ಲಿ 16 ತರಗತಿ ಕೊಠಡಿ, 01 ಸಿಬ್ಬಂದಿಗಳ ಕೊಠಡಿ, 01 ಮ್ಯಾಥ್ಸ್ ಲ್ಯಾಬ್, 01 ಫಿಸಿಕ್ಸ್ ಲ್ಯಾಬ್, 01 ಪರೀಕ್ಷಾ ಕೊಠಡಿ, ಬಾಲಕರಿಗಾಗಿ ಮತ್ತು ಬಾಲಕಿಯರಿಗಾಗಿ ಶೌಚಾಲಯವಿರುತ್ತದೆ. ಮೂರನೇ ಮಹಡಿಯಲ್ಲಿ 12 ತರಗತಿ ಕೊಠಡಿಗಳು, 02 ಸಿಬ್ಬಂದಿಗಳ ಕೊಠಡಿ, 01 ಲೈಬ್ರರಿ, 01 ಕೆಮಿಸ್ಟ್ರಿ ಲ್ಯಾಬ್, 01 ಬಯಾಲಜಿ ಲ್ಯಾಬ್ ಬಾಲಕರಿಗಾಗಿ ಮತ್ತು ಬಾಲಕಿಯರಿಗಾಗಿ ಶೌಚಾಲಯವಿರುತ್ತದೆ. ನಾಲ್ಕನೇ ಮಹಡಿಯಲ್ಲಿ 12 ತರಗತಿ ಕೊಠಡಿಗಳು, 01 ಸಿಬ್ಬಂದಿಗಳ ಕೊಠಡಿ, 01 ಸೆಮಿನಾರ್ ಹಾಲ್, 02 ಕಂಪ್ಯೂಟರ್ ಲ್ಯಾಬ್, ಬಾಲಕರಿಗಾಗಿ ಮತ್ತು ಬಾಲಕಿಯರಿಗಾಗಿ ಶೌಚಾಲಯವಿರುತ್ತದೆ.

-2-

- ಸದರಿ ಶಾಲಾ ಕಟ್ಟಡವನ್ನು Christ School (CBSE Syllabus), Dharmaram College P.O., Suddagunte Palya, Bangalore – 560029 ರಲ್ಲಿ ನಿರ್ಮಿಸಿರುವುದು ಕಂಡು ಬಂದಿರುತ್ತದೆ.
- ಕಟ್ಟಡಗಳ ಸುರಕ್ಷತೆಗೆ ಸಂಬಂಧಿಸಿದಂತೆ ಕಟ್ಟಡದ ಕಾಂಕ್ರಿಟ್ ಸದೃಢತೆಯ ಬಗ್ಗೆ Department of Civil Engineer UVCE, Bangalore University, Bangalore, ರವರು Rebound hammer test & Ultra Sonic test ಕೈಗೊಂಡು ವರದಿಯನ್ನು ನೀಡಿರುತ್ತಾರೆ.

ಸದರಿ ಸಂಸ್ಥೆಯವರು ನೀಡಿರುವ ಎಲ್ಲಾ ದಾಖಲೆಗಳನ್ನು ಪರಿಶೀಲಿಸಲಾಗಿ ಹಾಗೂ Department of Civil Engineer UVCE, Bangalore University, Bangalore, ರವರು ಕಟ್ಟಡವು ರಚನಾತ್ಮಕವಾಗಿ ಸುರಕ್ಷಿತವಾಗಿದೆಯೆಂದು ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ನೀಡಿರುತ್ತಾರೆ. ಸದರಿ ವರದಿಗಳನ್ನು ಹಾಗೂ ಕಟ್ಟಡವನ್ನು ಪರಿಶೀಲಿಸಲಾಗಿ ಕಟ್ಟಡದ ಆರ್.ಸಿ.ಸಿ. ಕಂಬ, ತೊಲೆ ಹಾಗೂ ಛಾವಣಿಯಲ್ಲಿ ಯಾವುದೇ ಬಿರುಕುಗಳು ಕಂಡು ಬಂದಿರುವುದಿಲ್ಲ ಹಾಗೂ ಕಟ್ಟಡವು ಮೇಲ್ನೋಟಕ್ಕೆ ಸುರಕ್ಷಿತವಾಗಿರುವುದು ಕಂಡು ಬಂದಿರುತ್ತದೆ. ಹಾಗೂ ಕಟ್ಟಡವು Structural Sound Condition ಇರುವುದಾಗಿ ಪರೀಕ್ಷೆ ವರದಿಗಳು ಕಂಡು ಬಂದಿರುವುದರಿಂದ ಹಾಗೂ ಕಟ್ಟಡವು ಮೇಲ್ನೋಟಕ್ಕೆ ಸುರಕ್ಷಿತವಾಗಿರುವುದು ಕಂಡು ಬಂದಿರುತ್ತದೆ. ಈ ಕೆಳಕಂಡ ಷರತ್ತುಗಳನ್ನು ಅನುಸರಿಸಲು ಸೂಚಿಸಲಾಗಿದೆ.

1. ಅಗ್ನಿಶಾಮಕ ಇಲಾಖೆ ಮತ್ತು ಇತರೆ ಸಂಬಂಧಪಟ್ಟ ಇಲಾಖೆಗಳ ಸಕ್ಷಮ ಪ್ರಾಧಿಕಾರಗಳಿಂದ ಅನುಮತಿ / ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ನಿಯಮಾವಳಿಗಳ ಅನ್ವಯ ನಿಗದಿತ ಸಮಯಗಳಲ್ಲಿ ಪಡೆಯತಕ್ಕದ್ದು.
2. ಕಟ್ಟಡವನ್ನು ಕಾಲಕಾಲಕ್ಕೆ ಉತ್ತಮ ಗುಣಮಟ್ಟದ ಸಾಮಗ್ರಿಗಳನ್ನು ಬಳಸಿ ತಜ್ಞರಿಂದ ವ್ಯವಸ್ಥಿತವಾಗಿ ನಿರ್ವಹಣೆ ಮಾಡತಕ್ಕದ್ದು.
3. ವಿದ್ಯಾರ್ಥಿಗಳ ಹಾಗೂ ಶಿಕ್ಷಕರ ಸುರಕ್ಷತೆಗೆ ಸಕಲ ಆದ್ಯತೆಯನ್ನು ನೀಡಿ ಸೂಕ್ತ ಸುರಕ್ಷತಾ ವ್ಯವಸ್ಥೆಯನ್ನು ಅಳವಡಿಸಿಕೊಳ್ಳತಕ್ಕದ್ದು.
4. ಕಟ್ಟಡದ ಸದೃಢತೆಗೆ ಧಕ್ಕೆಯಾಗುವಂತಹ ಯಾವುದೇ ಇತರೆ ಕಾಮಗಾರಿಗಳನ್ನು ಸಕ್ಷಮ ಪ್ರಾಧಿಕಾರದಿಂದ ಅನುಮತಿ ಪಡೆಯದೇ ಕೈಗೊಳ್ಳತಕ್ಕದ್ದಲ್ಲ. ಅನುಮತಿ ಪಡೆಯದೇ ಕೈಗೊಂಡಲ್ಲಿ ಪ್ರಮಾಣ ಪತ್ರವು ಆ ಕೂಡಲೇ ರದ್ದಾಗುತ್ತದೆ.
5. ಕುಡಿಯುವ ನೀರು ಹಾಗೂ ಶೌಚಾಲಯಗಳಲ್ಲಿ ಸದಾ ಸ್ವಚ್ಚತೆಯನ್ನು ಕಾಪಾಡಿಕೊಳ್ಳತಕ್ಕದ್ದು ಹಾಗೂ ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆಯಿಂದ ಶಾಲಾ ಕಾಲೇಜಿಗೆ ಸಂಬಂಧಿಸಿದ ಎಲ್ಲಾ ನಿರ್ದೇಶನ ಹಾಗೂ ನಿಯಮಾವಳಿಯನ್ನು ಕಡ್ಡಾಯವಾಗಿ ಪಾಲಿಸತಕ್ಕದ್ದು.

ಮೇಲೆ ತಿಳಿಸಲಾಗಿರುವ ಷರತ್ತುಗಳಿಗೊಳಪಟ್ಟು Christ School (CBSE Syllabus), Dharmaram College P.O., Suddagunte Palya, Bangalore - 560029 ಕಟ್ಟಡಕ್ಕೆ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು 2026-27ನೇ ಸಾಲಿನಲ್ಲಿ ನೀಡಲಾಗಿದೆ.

ತಮ್ಮ ವಿಶ್ವಾಸಿ,

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ನಂ. 1, ಕಟ್ಟಡಗಳ ಅಗ್ನಿ-ಸುರಕ್ಷತಾ ವಿಭಾಗ, ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಕೇಂದ್ರ
ಬೆಂಗಳೂರು-560 001

सत्यमेव जयते

INDIA NON JUDICIAL

Government of Karnataka

Rs. 100

e-Stamp

Certificate No.	:	IN-KA76691710028299Y
Certificate Issued Date	:	01-Sep-2026 12:44 PM
Account Reference	:	NONACC (FI)/ kaksfcl08/ SG PALYA/ KA-GN
Unique Doc. Reference	:	SUBIN-KAKAKSFCL0832167411308694Y
Purchased by	:	CHRIST SCHOOL CBSE
Description of Document	:	Article 4 Affidavit
Property Description	:	AFFIDAVIT
Consideration Price (Rs.)	:	0 (Zero)
First Party	:	CHRIST SCHOOL CBSE
Second Party	:	N A
Stamp Duty Paid By	:	CHRIST SCHOOL CBSE
Stamp Duty Amount(Rs.)	:	100 (One Hundred only)

S.G PALYA TPSWCL

Please write or type below this line

To,

The Principal,
Christ School (CBSE Syllabus),
Dharmaram College P.O.,
Suddagunte Palya.
Bangalore – 560 029.

NOTARY
Bangalore Metropolitan Area
GOVT. OF INDIA

Statutory Alert:

1. The authenticity of this Stamp certificate should be verified at 'www.shcilestamp.com' or using e-Stamp Mobile App of Stock Holding. Any discrepancy in the details on this Certificate and as available on the website / Mobile App renders it invalid.
2. The onus of checking the legitimacy is on the users of the certificate.
3. In case of any discrepancy please inform the Competent Authority.

Respected Sir,

Subject: Regarding issue of **Building Safety Certificate** of Christ School (CBSE Syllabus)

Reference: 1) Christ School (CBSE Syllabus), Bangalore, letter dated 17-08-2026

2) Government Order No: Lo. E/59/B.E.D/2019/Dated: 07-05-2022.

As mentioned above subject Christ School (CBSE Syllabus), Dharmaram College P.O., Suddagunte Palya, Bangalore-560029 required to provide building safety certificate for educational purposes is requested in their letter of reference (1) to provide building safety certificate. And the documents related to the said building will be submitted to this office.

Accordingly, the school building will be inspected on Date: 20-08-2026 in the presence of Head, Christ School (CBSE Syllabus). As per the Government order of reference (2), The Assistant Executive Engineer, No.1 Buildings Sub-division, V.V. Centre, Bangalore on that name the amount of Rs.5,000/- bearing Challan No: CR0826021600248777 submitted to this office.

The said building premises consist of 01 hall on the Ground Floor, 01 Principal's Room, 01 Prayer Hall, 01 Counselling Room, 03 Storerooms, 01 Staff Room, and 01 Vice Principal's Room, 05 classrooms, 01 auditorium, 01 conference hall, 01 Trust Office, and separate toilets for boys and girls. The first floor has 01 Staff Room, 16 classrooms, 02 storerooms, and separate toilets for boys and girls. The second floor has 16 classrooms, 01 Staff Room, 01 Mathematics Lab, 01 Physics Lab, 01 Examination Control Room, and separate toilets for boys and girls. The third floor has 12 classrooms, 02 Staff Rooms, 01 Library, 01 Chemistry Lab, 01 Biology Lab, and separate toilets for boys and girls. The fourth floor has 12 classrooms, 01 Staff Room, 01 Seminar Hall, 02 Computer Lab and separate toilets for boys and girls.

- Christ School (CBSE Syllabus), Dharmaram College P.O., Suddagunte Palya, Bangalore - 560 029 is found to have been built.
- Rebound hammer test & Ultra Sonic test has been conducted by the Department of Civil Engineering, UVCE, Bangalore University, Jnanabharati Campus, Bangalore -560056 and submitted the report on safety of the building.

All the documents given by the said organization have been verified and certified by the Department of Civil Engineer, UVCE, Jnanabharati, Bangalore University, Bangalore that the site is safe. The said reports and the building were inspected and R.C.C. of the building. No cracks were found in the pillars, beams and roof and the building was apparently safe. And since the test reports have found that the **building is in Structural Sound Condition** and the **Building is Apparently Safe.** The following conditions are suggested to be followed.

1. Permission/certificate should be obtained from the competent authorities of fire department and other concerned departments as per the rules within prescribed time.

2. The building should be systematically maintained by experts using good quality materials from time to time.

NOTARY
P.P.PAI B.A. LL.B
Bangalore
Metropolitan Area
Reg.No.6103
GOVT. OF INDIA

ದಸ್ತಾವೇಜು ಹಾಳೆ
Document Sheet

₹ 3/-

THE BANGALORE ADVOCATES' CO-OPERATIVE SOCIETY LTD.
BACSL

ತ X/6:

3. Safety of students and teachers should be given priority and appropriate safety system; it should be adopted.

4. Any other works which may affect the integrity of the building shall not be carried out without obtaining permission from the competent authority. If done without permission, building safety certificate will become cancel.

5. The parapet wall above the terrace is of low height and it is suggested to increase its height for safety reasons.

6. Cleanliness of drinking water and toilets should be maintained at all times and all directives and regulations related to schools and colleges should be compulsorily followed by the direction of Bangalore Municipal Corporation.

With the above-mentioned conditions, the **BUILDING SAFETY CERTIFICATE** is granted to said Christ School (CBSE Syllabus), Dharmaram College P.O., Suddagunte Palya, Bangalore 560029 for the year **2026-27.**

Your faithfully,

NOTARY P.P.P... BA LL.B ... Metropolitan Area Reg No.6103 GOVT OF INDIA

Translated Copy
SWORN TO BEFORE ME
02/09/2026
P.P.PAUL BA., LL.B
ADVOCATE AND NOTARY
GOVT. OF INDIA
22, P.J Philips Building
Chikkadugodi, Thavarekere P.O.
Bangalore - 560 034

Sl.No. 2491 Page 1616
Vol. V Date 02/09/2026

Principal
Christ School, Affl. No: 831274
Christ School Road, DRC Post,
Bengaluru - 560 029

Correspondent
Christ School, Affl. No: 831274
Christ School Road, DRC Post,
Bengaluru - 560 029